

Southern HAYWARD FAULT




Figure 4. Southern Hayward Fault Surface Displacement (1979-2001)